


## How to measure for Venoflex Fast Knee High Socks

The best time to measure is first thing in the morning

### How to measure for below knee socks

1. **Ankle (Cb)** measure the circumference at the ankle just above the bone
2. **Calf (Cc)** measure the circumference at the widest part of the calf

**Length (CD)** measure from the heel at the ground to just below the knee cap



Size	cB (cm)	cC (cm)
1	19-21	30-35
2	21-24	32-38
3	24-26	34-42
4	26-29	37-46

Length	Normal	Long
	Less Than 44cm	greater than 44cm

**Available in Compression 1 (10-15mmHg) and Compression 2 ( 20-36mmHg)**